



ಹಿಂದೂಸ್ತಾನ್ ಏರೋನಾಟಿಕ್ಸ್ ಲಿಮಿಟೆಡ್
ಪ್ರಧಾನ ಕಛೇರಿ
ಹಿಂದುಸ್ತಾನ ಏರೋನಾಟಿಕ್ಸ್ ಲಿಮಿಟೆಡ್
ಮುಖ್ಯಾಲಯ
HINDUSTAN AERONAUTICS LIMITED
CORPORATE OFFICE

CO/SEC/4(7)/2018/ BSE & NSE Filing/17

27th June, 2018

BSE Limited Listing Department Phiroze Jeejeebhoy Towers, Dalal Street, Mumbai – 400 001	National Stock Exchange of India Ltd Listing Department Exchange Plaza, 5 th Floor, Plot No C/1, G Block, Bandra-Kurla Complex, Bandra (E) Mumbai – 400051
--	--

Dear Sir/ Madam,

Sub: Media Release

Ref: BSE Scrip Code: 541154, NSE Symbol: HAL

In terms of Regulation 30 of the SEBI (LODR) Regulations, 2015, we are enclosing herewith a copy of the media release titled “**information on Su-30 MKI Crash**” being issued to the media.

2. This is for information and record, please.

Thanking you,

Yours Faithfully
For Hindustan Aeronautics Ltd

(G V Sessa Reddy)
Company Secretary & Compliance Officer

15/1, ಕಬ್ಬನ್ ರೋಡ್, ಬೆಂಗಳೂರು - 560 001, ಭಾರತ, 15/1, ಕಬ್ಬನ್ ರೋಡ್, ಬೆಂಗಳೂರು - 560 001, ಭಾರತ
15/1, Cubbon Road, Bangalore - 560 001, India

ದೂರವಾಣಿ (ಫೋನ್) Ph. : +91-80-2232 0001, 2232 0475, ಫ್ಯಾಕ್ಸ್ (ಫೇಕ್ಸ್) Fax : +91-80-2232 0758

ಇಮೇಲ್ (ಇಮೇಲ್) Email: cosec@hal-india.co.in

CIN : L35301KA1963GOI001622



ಹಿಂದೂಸ್ತಾನ್ ಏರೋನಾಟಿಕ್ಸ್ ಲಿಮಿಟೆಡ್
ಪ್ರಧಾನ ಕಛೇರಿ

ಹಿಂದುಸ್ತಾನ ಏರೊನಾಟಿಕ್ಸ್ ಲಿಮಿಟೆಡ್

ಮುಖ್ಯಾಲಯ

HINDUSTAN AERONAUTICS LIMITED
CORPORATE OFFICE

No. HAL/CorpCom/1-1/18

27th June 2018

Media Release:

Information on Su-30 Mkl Crash

Bengaluru, June 27, 2018: Su 30 Mkl, produced at HAL Nashik crashed during a sortie in local flying area of Ozar (Nashik) Airport today at 11 hrs. It was piloted by Wg Cdr Prashant Nair accompanied by Sqn Ldr L Biswal (Flight Test Engineer). Both ejected safely.

The Board of Investigation has been ordered to find out the exact cause.

Yours faithfully,
For Hindustan Aeronautics Ltd.

G. Sutar
(Gopal Sutar)

Chief of Media Communications

www.hal-india.co.in